Table 2. Description of Potential Work Practice Regulatory Options			
Interior containment	Before beginning the renovation, the firm must isolate the work area so that no dust or debris leaves the work area while the renovation is being performed.		
Interior work practices	Remove all objects from the work area, including furniture, rugs, and window coverings, or cover them with plastic sheeting or other impermeable material with all seams and edges taped or otherwise sealed.		

Standards for post-renovation cleaning verification, if required:

A certified renovator must perform a visual inspection to determine whether dust, debris or residue is still present. If dust, debris or residue is present, these conditions must be removed by re- cleaning and another visual inspection must be performed.

After a successful visual inspection, a certified renovator must:

A. Verify that each windowsill in the work area has been adequately cleaned, using the following procedure.

	cloth. After this wipe, that section of the surface has been adequately cleaned.				
	When the work area passes the post-renovation cleaning verification, remove the warning signs.				
Exterior Cleaning	After the renovation has been completed, the firm must clean the work area until no dust, debris or residue remains. Collect all paint chips and debris and, without dispersing any of it, seal this material in a heavy-duty bag. Remove the protective sheeting. Mist the sheeting before folding it, fold the dirty side inward, and either tape shut to seal or seal in heavy-duty bags. Sheeting used to isolate contaminated rooms from non-contaminated rooms must remain in place until after the cleaning and removal of other sheeting. Dispose of the sheeting as waste. A certified renovator must perform a visual inspection to determine whether dust, debris or residue is still present on surfaces in and below the work area, including windowsills and the ground.				
	If dust, debris or residue is present, these conditions must be eliminated and another visual inspection must be performed.				
	When the area passes the visual inspection, remove the warning signs.				
Note: Work practices are verification is required.	cleaning				